

Dye migration (from non-colour fast clothing or accessories).



Cuts or abrasions not noted at the pre-delivery inspection (PDI).




Ingress / egress wear.




Poor appearance. Leather cracking or ageing.



Cigarette burns.



Pen marks or other driver-induced defects.



Soiled.



Spillages or staining.

